

Measure E Bond Program MJC Auditorium Alterations/Addition

CONSTRUCTION UPDATE

Issue No. 27

MAY 11, 2007

1. Work performed during week of 05/07/07:

- a. Continued metal stud framing at north side addition.
- b. Installed south side addition underground plumbing.
- c. Completed south side addition 2nd floor metal decking.
- d. Continued equipment installation in mechanical room.
- e. Completed metal stud framing in basement.
- f. Started fire sprinkler system at north side addition.
- g. Continued duct installation in basement and 1st floor.
- h. Started duct installation at north side addition.
- i. Installing deck inserts at south side addition.
- j. Continued plywood sheathing at north side addition.
- k. Started underslab rock at south side addition.



North Side Addition Exterior Framing

2. Work anticipated for week of 05/14/07:

- a. Backfill west side vault, pipe tunnels and stairs.
- b. Start remaining lead paint removal in auditorium.
- c. Continue metal stud framing at north side additon.
- d. Continue mechanical and electrical work in basement and 1st floor.
- e. Start 1st floor slab reinforcement at south side addition.
- f. Pour south side addition restroom curbs.
- q. Continue MEP installation at north side addition.

2007/05/07

Cutting Metal Deck at South Side Addition

3. Activities that may impact campus operations:

- a. Access: East sidewalk closed at Music/Arts Buildings
- b. Noise: Construction equipment on south site.
- c. Parking: Less South Street parking spaces for deliveries.
- d. Power outages: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- g. Dust: No unusual dust is expected.

