

Measure E Bond Program MJC Auditorium Alterations/Addition

CONSTRUCTION UPDATE

Issue No. 28

MAY 18, 2007

1. Work performed during week of 05/014/07:

- a. Continued metal stud framing at north side addition.
- b. Installed south side addition 1st floor reinforcement.
- c. Installed south side addition 2nd floor reinforcement.
- d. Back filled west side vault and tunnels.
- e. Staging for start of south side addition metal framing.
- f. Finished fire sprinkler rough-in at north side addition.
- g. Continued chilled water pipe installation in basement.
- h. Continued duct installation at north side addition.
- i. Started additional lead paint removal in auditorium.
- j. Stated retrofit steel installation at fly loft.
- k. Poured areas of concrete floor at south side addition.



North Side Addition Plywood Sheathing

2. Work anticipated for week of 05/21/07:

- a. Pour south side addition slab-on-grade.
- b. Pour south side addition 2nd floor slab.
- c. Start installation of west side stairs.
- d. Continue mechanical and electrical work in basement and 1st floor.
- e. Continue lead paint removal above auditorium ceiling.
- f. Continue metal framing at north side addition.
- a. Continue MEP installation at north side addition.

100-705/16

South Side Addition 2nd Floor Reinforcement

3. Activities that may impact campus operations:

- a. Access: East sidewalk closed at Music/Arts Buildings
- b. Noise: Construction equipment on south site.
- c. Parking: Less South Street parking spaces for deliveries.
- d. Power outages: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- g. Dust: No unusual dust is expected.



