

Measure E Bond Program MJC Auditorium Alterations/Addition

CONSTRUCTION UPDATE

Issue No. 29

MAY 25, 2007

1. Work performed during week of 05/21/07:

- a. Continued metal stud framing at north side addition.
- b. Poured south side addition 1st floor slab-on-grade.
- c. Poured south side addition 2nd floor slab.
- d. Started installation of west side stairs.
- e. Started metal stud framing at east side stairs.
- f. Continued fire sprinkler rough-in at 1st floor.
- g. Continued chilled water pipe installation in basement.
- h. Continued duct installation at south side addition.
- i. Completed lead paint removal in auditorium.
- j. Continued retrofit steel installation at fly loft.
- k. Installed gas line through south parking lot.



Placing South Side Addition 2nd Floor Concrete

2. Work anticipated for week of 05/28/07:

- a. Pour Little Theater slab-on-grade.
- b. Start scaffolding for south side addition metal stud framing.
- c. Install reinforcement for concrete pads at south side addition roof
- d. Pour footings along E1 and 6 lines on the west side of the building.
- e. Continue mechanical and electrical work in basement and 1st floor.
- f. Start exterior metal sheathing at north side addition.
- g. Continue MEP installation at north and south side additions.

West Side Stairs and Footing Form Installation

3. Activities that may impact campus operations:

- a. Access: East sidewalk closed at Music/Arts Buildings
- b. Noise: Construction equipment on south site.
- c. Parking: Less South Street parking spaces for deliveries.
- d. Power outages: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- g. Dust: No unusual dust is expected.

