

Measure E Bond Program MJC Auditorium Alterations/Addition

CONSTRUCTION UPDATE

Issue No. 33

JUNE 22, 2007

2.

1. Work performed during week of 06/18/07:

- a. Started installation of fire sprinkler pipes at 2nd floor of south side addition.
- b. Continued off site improvements.
- c. Continued framing at 2nd floor of south side addition.
- d. Continued ceiling framing at loading dock.
- e. Continued framing at 1st floor of south side addition.
- f. Continued MEP work in basement and north side.
- g. Continued electrical rough in at north side addition.
- h. Finished spot priming of structural steel.



a. Start site demolition on the south side of South Drive east end. Framing Perimeter Walls at South Side Addition

Work anticipated for week of 06/25/07:

- b. Continue south side addition metal stud framing.
- c. Continue A/V conduit installation above auditorium ceiling.
- d. Continue MEP work in basement and north side addition.
- e. Continue off site improvements along South Drive and Stoddard Ave.
- f. Finish roof decking at north side addition.



South Side Addition

3. Activities that may impact campus operations:

- a. Access: No access to south sidewalk along South Drive and north sidewalk along Sttodard Ave.
- b. Noise: Construction equipment along South Drive and Sttodard Ave.
- c. Parking: Fewer parking spaces along South Drive.
- d. Power outages: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- g. Dust: Due to off site improvements along South Drive.

