

## Measure E Bond Program MJC Auditorium Alterations/Addition

CONSTRUCTION UPDATE

Issue No. 25

#### **APRIL 27, 2007**

#### 1. Work performed during week of 04/23/07:

- a. Continued metal stud framing at north building.
- b. Continued conduit installation underside of 2<sup>nd</sup> floor.
- c. Completed erection of south building structural steel.
- d. Continued equipment installation in mechanical room.
- e. Continued metal stud framing in basement.
- f. Continued fire sprinkler system installation.
- g. Continued duct installation in basement.
- h. Continued air and water lines installation in basement.
- i. Continued metal deck installation at south building.
- j. Started drywall installation in basement.
- k. Completed south side stem walls.



**North Side Addition Wall Framing** 

#### 2. Work anticipated for week of 04/30/07:

- a. Continue metal deck installation at south building.
- b. Start site grading at south building.
- c. Continue metal stud framing at north building.
- d. Continue mechanical and electrical work in basement.
- e. Continue metal decking at south building.
- f. Pour west side tunnel roof and complete backfill.
- g. Finish MEP installation at south building interstitial space.

# 2007 726

Structural Steel at South Building

### 3. Activities that may impact campus operations:

- a. Access: No access problems anticipated
- b. Noise: Construction equipment on south site.
- c. Parking: Less South Street parking spaces for deliveries.
- d. Power outages: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- q. Dust: No unusual dust is expected.

