

Measure E Bond Program MJC Auditorium Alterations/Addition

CONSTRUCTION UPDATE

Issue No. 30

JUNE 1, 2007

1. Work performed during week of 05/28/07:

- a. Continued metal stud framing at north side addition.
- b. Poured south side addition roof pads.
- c. Poured E.1 and 6 line footings and stem walls.
- d. Completed installation of west side stairs to roof.
- e. Continued metal stud framing at east side stairs.
- f. Continued fire sprinkler rough-in at 1st floor.
- g. Continued chilled water pipe installation in basement.
- h. Continued duct installation at south side addition.
- i. Erecting south side addition east side scaffolding.
- j. Installed catwalk beams in fly loft.
- k. Started roof decking at north side addition.



South Side Addition Concrete Roof Pads

2. Work anticipated for week of 06/04/07:

- a. Pour Little Theater slab-on-grade.
- b. Pour sidewalk on east side of Music Building.
- c. Continue A/V conduit installation above auditorium ceiling
- d. Continue ductwork and sprinkler piping at 1st floor of south side addition.
- e. Continue mechanical and electrical work in basement.
- f. Complete plywood sheathing at north side addition.
- g. Start ceiling framing at east side loading dock area.



West Side Stairs and Footing Form Installation

3. Activities that may impact campus operations:

- a. Access: East sidewalk closed at Music/Arts Buildings
- b. Noise: Construction equipment on south site.
- c. Parking: Less South Street parking spaces for deliveries.
- d. Power outages: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- g. Dust: No unusual dust is expected.

