

## Measure E Bond Program MJC Auditorium Alterations/Addition

**CONSTRUCTION UPDATE** 

Issue No. 31

#### **JUNE 8, 2007**

#### 1. Work performed during week of 06/04/07:

- a. Continued metal stud framing at north side addition.
- b. Poured Little Theater slab-on-grade.
- c. Poured topping slabs at 2<sup>nd</sup> floor restrooms.
- d. Poured Mason System floors in Rooms 228 and 229.
- e. Continued metal stud framing at east side stairs.
- f. Continued fire sprinkler rough-in at 1st floor.
- g. Continued chilled water pipe installation in basement.
- h. Continued duct installation at south side addition.
- i. Backfilled around west side stairs.
- j. Installed A/V conduit west side of auditorium.
- k. Finished roof decking at north side addition.



Lath for Installation at North Side Addion

#### 2. Work anticipated for week of 06/11/07:

- a. Start installation of lath at north side addition.
- b. Continue south side addition metal stud framing at 1<sup>st</sup> floor.
- c. Continue A/V conduit installation above auditorium ceiling
- d. Continue ductwork and sprinkler piping at 1<sup>st</sup> floor of south side addition.
- e. Continue mechanical and electrical work in basement.
- f. Start fireproofing structure steel at the south side addition.
- g. Start ceiling framing at east side loading dock area.

# 2007/06/04

**New Sidewalk East Side of Music Building** 

### 3. Activities that may impact campus operations:

- a. Access: East sidewalk closed at Music/Arts Buildings
- b. Noise: Construction equipment on south site.
- c. Parking: Less South Street parking spaces for deliveries.
- d. Power outages: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- g. Dust: No unusual dust is expected.

