

## Measure E Bond Program MJC Auditorium Alterations/Addition

CONSTRUCTION UPDATE

Issue No. 13

#### **FEBRUARY 2, 2007**

#### 1. Work performed during week of 01/29/07:

- a. Delivered steel channels and bolted to north side of building.
- b. Delivered 1<sup>st</sup> load of north side structural steel.
- c. Poured floor slab in electrical room.
- d. Continued wall forms at west side elevator/stairs.
- e. Constructed scaffolding at west side elevator/stairs.
- f. Poured wall at east side stairs.
- g. Completed wall rebar at stage area.
- h. Installed rebar at wall openings to be filled.
- i. Demolished slab for opening to basement from back stage.
- j. Graded at Little Theater and excavated adjacent footings.
- k. Cleaning ductwork and prefabricating electrical conduit.



Scaffolding at West Side Elevator/Stairs

#### 2. Work anticipated for week of 02/05/07:

- a. Set-up crane, deliver metal decking and start erection of north side steel.
- b. Form and pour footings west of Little Theater.
- c. Continue wall forms at west side elevator/stairs.
- d. Excavate west side deep footing near elevator/stairs
- e. Strip east side stair wall forms, waterproof wall and backfill.
- f. Continue prefabricating electrical conduit.
- g. Continue cleaning ductwork.

# a. Acceb. Nois c. Park d. Pow e. Wat f. Odo

North Side Steel Channels Bolted Building

### 3. Activities that may impact campus operations:

- a. Access: Guarded access at South Street during steel erection.
- b. Noise: Construction equipment for steel erection and sawcutting.
- c. Parking: Fewer South Street parking spaces for steel erection.
- d. Power out: None anticipated.
- e. Water off: None anticipated.
- f. Odors: No unusual odors are expected.
- g. Dust: No unusual dust is expected.

If there are any questions or concerns contact Kitchell CEM, Measure E Bond Construction Manager, located at 429A Tully Road, Room 103, Modesto CA 95354 Tel: 575-6724 Email shall@kitchell.com

